Summary of Facility Information in the County of Garfield

Owner Name and Address: Farmers Union Oil Co Jordan PO Box 449 Jordan MT 59337 Phone: (406) 557-2215

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------------------|-------------------------|---------------|-------|----------------|
| 1705702 | Farmers Union Oil Co Jordan | MT Highway 200 | Jordan | 59337 | (406) 557-2215 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/OverI/C |
|-----------------------------|--------------|----------------------|---------------------|---|-----------------------------------|--------------|---|----------------------|
| 6 / 06 Currently In Use | 941 | 12/1/1998 07 / No | Gasoline 12,000 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Pressurized | (ABCDEFOHIJKL B (DEFOHIJKL) | Yes Yes Yes Yes |
| 7 / 07 Currently In Use | 942 | 12/1/1998 07 / No | Gasoline 4,100 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Pressurized | B DEF H J K L | Yes Yes Yes Yes |
| 8 / 08 Currently In Use | 943 | 12/1/1998 07 / No | Diesel 4,100 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Safe Suction | ABCDEF®HIJKL B DEF@HI®KL | Yes Yes Yes Yes |
| 9 / 09 Currently In Use | 944 | 12/1/1998 07 / No | Diesel 3,760 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Pressurized | (ABCDEFOHIJKL B DEFOHIJKL | Yes Yes Yes Yes |
| 10 / 10 Currently In Use | 945 | 12/1/1998 07 / No | Diesel 7,900 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Safe Suction | (ABCDEF@HIJKL B DEFGHI@KL | Yes Yes Yes Yes |
| 11 / 11 Currently In Use | 946 | 12/1/1998 07 / No | Diesel 4,100 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | Pressurized | (ABCDEFOHIJKL B DEFOHIJKL | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | SIR | K Deferred |
|-------------------------------|---------------------|--------------------|--------------------------------|-----------------|--------------|
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Report Generation Date: 7/3/2006 Page 1 of 3

Summary of Facility Information in the County of Garfield

Owner Name and Address: Fellmans Hardware Inc PO Box 344 Jordan MT 59337 Phone: (406) 557-2206

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------------|-------------------------|----------------------|-------|----------------|
| 1710707 | Fellmans Hardware Inc | MT Highway 200 | Jordan | 59337 | (406) 557-2392 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/OverI/C |
|----------------------------|--------------|----------------------|---------------------|---|-----------------------------------|-------------|---|----------------------|
| 5 / 05 Currently In Use | 4311 | 6/1/2001 05 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | ABC●EFGHIJKL B DEF●HIJKL | Yes Yes Yes Yes |
| 6 / 06 Currently In Use | 4312 | 6/1/2001 05 / No | Gasoline 4,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | B DEE@HIJKU | Yes Yes Yes Yes |
| 7 / 07 Currently In Use | 4313 | 6/1/2001 05 / No | Diesel 4,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | ABCOEFGHIJKL B DEFOHIJKL | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | SIR | K Deferred |
|-------------------------------|---------------------|--------------------|--------------------------------|-----------------|--------------|
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Report Generation Date: 7/3/2006 Page 2 of 3

Summary of Facility Information in the County of Garfield

Owner Name and Address: Jerry & Lilly Johnston Highway 200 & Foster St Jordan MT 59337 Phone: (406) 557-2805

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone | |
|-----------|---------------|----------------------------|---------------|-------|----------------|--|
| 1711117 | 6 Ds Inc | MT Highway 200 & Foster St | Jordan | 59337 | · | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/OverI/C |
|----------------------------|--------------|----------------------|---------------------|---|---------------------------------------|-------------|---|-------------------------|
| 1 / S1 Currently in Use | 2307 | 1/1/1970 36 / Ye | Gasoline 12,051 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Not Listed | ABCDEFGHIJOL BDEFGHIJOO | Yes Yes Yes Yes |
| 3 / S3 Currently in Use | 2309 | 1/1/1970 36 / Ye | Gasoline 6,082 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic None | Not Listed | ABCDEFGHIJOL B DEFGHIJKO | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | SIR | K Deferred |
|-------------------------------|---------------------|--------------------|--------------------------------|-----------------|--------------|
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Report Generation Date: 7/3/2006 Page 3 of 3